

Xikar 833Xi PuroTemp Hygrometer - Rectangular

Instructions for Use

XIKAR PuroTemp™ Digital Rectangular Hygrometer / Thermometer will accurately report humidity to +/- 2% at 70% RH (relative humidity) and temperature to 1 degree Fahrenheit / Celsius. To activate this unit, simply remove the vinyl tab located in the battery door on the bottom left of the unit. The LED screen should turn on and show humidity and temperature readings.

If the screen does not turn on, remove the battery by opening the cover located on the back of the unit. Make sure the battery is installed properly and makes contact with the silver metal contact. If the unit will not turn on, replace the battery.

To switch between Celsius and Fahrenheit display, simply press the °C / °F button located on the front of the hygrometer.


Min / Max Feature

Pressing the Min / Max button twice displays the % Min and % Max on screen. The small % Min and % Max on-screen display shows the lowest minimum and highest maximum humidity recorded over the life of the battery or until the Min / Max button is pressed again. Pressing the Min / Max button while % Min and % Max show on screen will reset both readings to current readings on large display.

Features

Item # 833XI

Measures 2.125" L x 3.375" W x .375" D
Accurate to +/- 2% at 70% humidity



Min / Max

Displays temperature in °C / °F

Lifetime Guarantee
XIKAR, Inc.
866-676-7380
WWW.XIKAR.COM
Made in China

The Xikar logo, featuring a stylized star or asterisk symbol to the left of the word 'XIKAR' in a bold, sans-serif font.